AML-SW3-WiFi6 - Bug #3989

3.8.4.1 ctcapd.wifi.mesh的 setmeshroaming

02/25/2026 14:33 -

Status:	New	**Start date:**	02/25/2026
Priority:	Normal	**Due date:**	
Assignee:		**% Done:**	0%
Category:		**Estimated time:**	0.00 hour
Target version:		**Spent time:**	0.00 hour
:	#7 SMP PREEMPT Tue Feb 10 14:35:51 CST 2026	:	100%

Description

1.mesh
ubus call ctcapd.wifi.mesh getmeshroaming

1.2mesh{"80211k":"0/1","80211v":"0/1","80211r":"0/1","2Grssi_thr":,"5Grssi_thr":,"rssi_diff":}

/ # ubus call ctcapd.wifi.mesh getmeshroaming
Command failed: Method not found

Files

d8cb7f61f2024e357f1879293ff8687a.png	8.97 KB	02/25/2026	