

1G_wifi - Bug #3313

3.2.4 IP

03/28/2025 12:02 -

Status:	Feedback	Start date:	03/28/2025
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
	20250326150244		100%
Description			
1.saf console 2.MAC { "RPCMethod": "NewDevice", "ID": "30e06488-efd0-484f-ac63-236061e1802b", "Enable": "1", "Sequenceld": "1234ABCD" } 3.PC 1.2 2.3PC 3.4 3.IP			

History

#1 - 04/02/2025 15:33 -

- Status changed from New to Feedback

```
1. cat /etc/hi_version
chip name      :emei_v500
product name   :ctc_hgu
glb version type :release
boot version type :debug
sdk version type :release
kernel version type:release
hgw version type :release
product version :HSAN_3.5.12.linux0
git version    :2b7533b8
flash type     :spi
release time   :20250401152636
software version :V1.0.0
hardware version :V1.0.0

2025-04-02 15:31:15.662 [INFO] >
{"RPCMethod":"NewDeviceNotification","ID":"c48ebdc5-9aba-461c-82fc-4640803daa5e","DevList":[{"Time":"20250402153115","DevName":"","DevType":"","MAC":"20626650A802","IP":"192.168.1.31","ConnectType":"0","Port":"1","Brand":"","OS":""}]} (234)
2025-04-02 15:31:15.665 [INFO] < {"Result":0,"Ack":"NewDeviceNotification","ID":"c48ebdc5-9aba-461c-82fc-4640803daa5e"} (86)
2025-04-02 15:31:15.681 [INFO] >
{"RPCMethod":"NewDeviceNotification","ID":"e3b81c07-16aa-4eae-bb3b-b5d00dcf36bb","DevList":[{"Time":"20250402153115","DevName":"","DevType":"","MAC":"20626650A801","IP":"192.168.1.30","ConnectType":"0","Port":"1","Brand":"","OS":""}]} (234)
2025-04-02 15:31:15.684 [INFO] < {"Result":0,"Ack":"NewDeviceNotification","ID":"e3b81c07-16aa-4eae-bb3b-b5d00dcf36bb"} (86)
```

Files

0000_20250328120147.png	223 KB	03/28/2025	00 0
-------------------------	--------	------------	------