

# WIFI6\_AP - Bug #3961

## 4.2.3.1 wifitimer

02/11/2026 14:41 -

<b>Status:</b>	New	<b>Start date:</b>	02/11/2026
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Created:</b>	SMP Fri Feb 6 10:17:44 CST 2026	<b>Progress:</b>	100%

### Description

1 wifitimer

```
{ "type": "cfg", "sequence": 0, "mac": "081074000001", "set": { "mode": "sync", "wifitimer": { "weekday": "1", "time": "18:00", "enable": "0", "weekday": "5", "time": "18:00", "enable": "1" } } }
```

```
{ "type": "cfg", "sequence": 0, "mac": "081074000001", "set": { "mode": "sync", "wifitimer": { "weekday": "6", "time": "14:35", "enable": "0", "weekday": "6", "time": "14:45", "enable": "1" } } }
```

2 timer list

ubus call ctcapd.wifi.timer list

1

```
{  
  "ctcapd.wifi.timer": [  
    {  
      "idx": 1,  
      "weekday": "1",  
      "time": "18:00",  
      "enable": "no",  
      "SSIDMask": 3855  
    },  
    {  
      "idx": 2,  
      "weekday": "5",  
      "time": "18:00",  
      "enable": "yes",  
      "SSIDMask": 3855  
    }  
  ]  
}
```

```
2026-02-11 14:33:21.168: [elinkclt] ubus_invoke_debug: o: ctcapd.wifi.timer.1, m: set  
2026-02-11 14:33:21.168: [elinkclt] {"weekday": "3", "time": "14:35", "enable": "no"}  
2026-02-11 14:33:21.168: [elinkclt] {"result": "1", "fail_reason": "Parameter SSIDMask is NULL. Please try again.\n"}  
2026-02-11 14:33:21.168: [elinkclt] ubus_invoke_debug: o: ctcapd.wifi.timer.2, m: set  
2026-02-11 14:33:21.169: [elinkclt] {"weekday": "3", "time": "14:45", "enable": "yes"}  
2026-02-11 14:33:21.169: [elinkclt] {"result": "1", "fail_reason": "Parameter SSIDMask is NULL. Please try again.\n"}  
2026-02-11 14:35:09.705: [elinkclt] ubus_invoke_debug: o: ctcapd.wifi.timer, m: list  
2026-02-11 14:35:09.706: [elinkclt]  
{ "ctcapd.wifi.timer": { "idx": 1, "weekday": "1", "time": "18:00", "enable": "no", "SSIDMask": 3855 }, { "idx": 2, "weekday": "5", "time": "18:00", "enable": "yes", "SSIDMask": 3855 } }  
2026-02-11 14:35:09.706: [elinkclt] ubus_invoke_debug: o: ctcapd.wifi.timer.1, m: set  
2026-02-11 14:35:09.706: [elinkclt] {"weekday": "6", "time": "14:35", "enable": "no"}  
2026-02-11 14:35:09.707: [elinkclt] {"result": "1", "fail_reason": "Parameter SSIDMask is NULL. Please try again.\n"}  
2026-02-11 14:35:09.707: [elinkclt] ubus_invoke_debug: o: ctcapd.wifi.timer.2, m: set  
2026-02-11 14:35:09.707: [elinkclt] {"weekday": "6", "time": "14:45", "enable": "yes"}  
2026-02-11 14:35:09.707: [elinkclt] {"result": "1", "fail_reason": "Parameter SSIDMask is NULL. Please try again.\n"}
```

### History

#1 - 03/16/2026 18:26 - [ ] [ ]

- Status changed from New to Resolved

- Assignee changed from [ ] [ ] to [ ] [ ]

[ ] [ ] [ ] [ ]

#2 - 03/20/2026 11:51 - [ ] [ ]

- Status changed from Resolved to New

#2 SMP Wed Mar 18 18:49:44 CST 2026 [ ] [ ] [ ] [ ] [ ] [ ]