

WIFI6_AP - Bug #3964

4.2.3.1 wifi

02/11/2026 15:22 -

Status:	Closed	Start date:	02/11/2026
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Created:	SMP Fri Feb 6 10:17:44 CST 2026	Updated:	100%

Description

1

```
{ "type": "cfg", "sequence": 0, "mac": "081074000001", "set": { "wifi": { "radio": { "mode": "2.4G", "channel": 11, "bandwidth": "20", "wifimode": "b/g/n", "txpower": "0"}, "ap": { "apidx": 0, "enable": "yes", "ssid": "test", "key": "12345678", "auth": "wpapswpa2psk", "encrypt": "aes"} } }, { "radio": { "mode": "5G", "channel": 0, "bandwidth": "20", "wifimode": "a/n/ac", "txpower": "0"}, "ap": { "apidx": 0, "enable": "yes", "ssid": "testElink-5G", "key": "12345678", "auth": "wpapswpa2psk", "encrypt": "aes"} } }, "mode": "set", "status": { "wifi": { "radio": { "mode": "2.4G", "channel": 0}, {"radio": { "mode": "5G", "channel": 0}} } }
```

2 web wifi

1 wifi

web

2026-02-11 15:15:01.891 [INFO] (elink) <-

```
{ "type": "cfg", "sequence": 0, "mac": "081074000001", "set": { "wifi": { "radio": { "mode": "2.4G", "channel": 11, "bandwidth": "20", "wifimode": "b/g/n", "txpower": "0"}, "ap": { "apidx": 0, "enable": "yes", "ssid": "test", "key": "12345678", "auth": "wpapswpa2psk", "encrypt": "aes"} } }, { "radio": { "mode": "5G", "channel": 0, "bandwidth": "20", "wifimode": "a/n/ac", "txpower": "0"}, "ap": { "apidx": 0, "enable": "yes", "ssid": "testElink-5G", "key": "12345678", "auth": "wpapswpa2psk", "encrypt": "aes"} } }, "mode": "set", "status": { "wifi": { "radio": { "mode": "2.4G", "channel": 0}, {"radio": { "mode": "5G", "channel": 0}} } } (576)
```

2026-02-11 15:15:01.904 [INFO] wifi config no changed

2026-02-11 15:15:01.904 [INFO] (elink) -> { "type": "ack", "sequence": 0, "mac": "081074000001", "errcode": 0, "errmsg": "" } (72)

2026-02-11 15:15:01.892: [elinkctl] ubus_invoke_debug: o: ctcapd.wifi.1, m: get

2026-02-11 15:15:01.893: [elinkctl]

```
{ "ctcapd.wifi.1": { "channel": 11, "txpower": "0", "currentchannel": 11, "bandwidth": "0", "enable": "no", "load": "100", "mode": "b/g/n", "auth": "open/shared/wpapswpa2psk/wpa2psk/wpa_wpa2_psk/wpa_enterprise/wpa2_enterprise/wpa_wpa2_enterprise/wps/wpa3sae/wpa2_wpa3", "backgroundnoise": "0" }
```

2026-02-11 15:15:01.893: [elinkctl] ubus_invoke_debug: o: ctcapd.wifi.2, m: get

2026-02-11 15:15:01.895: [elinkctl]

```
{ "ctcapd.wifi.2": { "channel": 0, "txpower": "0", "currentchannel": 0, "bandwidth": "0", "enable": "no", "load": "100", "mode": "a/n/ac", "auth": "open/shared/wpapswpa2psk/wpa2psk/wpa_wpa2_psk/wpa_enterprise/wpa2_enterprise/wpa_wpa2_enterprise/wps/wpa3sae/wpa2_wpa3", "backgroundnoise": "0" }
```

2026-02-11 15:15:01.896: [elinkctl] ubus_invoke_debug: o: ctcapd.devinfo, m: get

2026-02-11 15:15:01.901: [elinkctl]

```
{ "ctcapd.devinfo": { "mac": "*****", "vendor": "ZNXT", "model": "ZN-E5", "swversion": "V2.0.0", "hdversion": "V2.0.0", "sn": "*****", "ipaddr": "*****", "url": "http://router.ctc", "wireless": "no", "dualband": "yes", "triband": "no", "workmode": "bridge", "suggestworkmode": "any", "mesh": 1, "usb": "no", "vpn": "no", "ifversion": "3.0", "ctei": "*****", "lanports": [1, 2, 3], "wanports": [4], "devtype": "AP", "description": "CTCC BE3600 ROUTER" }
```

2026-02-11 15:15:01.901: [elinkctl] ubus_invoke_debug: o: ctcapd.wifi.1.ap.1, m: get

2026-02-11 15:15:01.902: [elinkctl]

```
{ "ctcapd.wifi.1.ap.1": { "enable": "yes", "hide": "0", "ssid": "*****", "key": "*****", "auth": "wpapswpa2psk", "encrypt": "aes", "bssid": "*****", "accessmode": "0", "accessrule": "0", "allowedipport": "", "usbandwidth": "0", "dsbandwidth": "0" }
```

2026-02-11 15:15:01.903: [elinkctl] ubus_invoke_debug: o: ctcapd.wifi.2.ap.1, m: get

2026-02-11 15:15:01.904: [elinkctl]

```
{ "ctcapd.wifi.2.ap.1": { "enable": "yes", "hide": "0", "ssid": "*****", "key": "*****", "auth": "wpapswpa2psk", "encrypt": "aes", "bssid": "*****", "accessmode": "0", "accessrule": "0", "allowedipport": "", "usbandwidth": "0", "dsbandwidth": "0" }
```

History

#1 - 03/16/2026 18:51 -

- Status changed from New to Resolved

- Assignee changed from [redacted] to [redacted]

elink [redacted] [redacted]ubus [redacted]set [redacted] [redacted]

#2 - 03/25/2026 15:47 - [redacted]

- Status changed from Resolved to Closed

#2 SMP Tue Mar 17 17:26:31 CST 2026 [redacted]