

WIFI6_AP - Bug #3967

4.2.3.6 wps wps

02/11/2026 15:50 -

Status:	Closed	Start date:	02/11/2026
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Created:	SMP Fri Feb 6 10:17:44 CST 2026	Progress:	100%

Description

1 {"type":"cfg","sequence":0,"mac":"mac","set":{"mode":"set","wpsswitch":{"status":"ON"}}}

2 wps

1 wps

wps

2026-02-11 15:49:45.366 [INFO] (elink) <-

{"type":"cfg","sequence":0,"mac":"081074000001","set":{"mode":"set","wpsswitch":{"status":"ON"}}} (112)

2026-02-11 15:49:45.379 [INFO] (elink) -> {"type":"ack","sequence":0,"mac":"081074000001","errcode":0,"errmsg":""} (72)

/ # commit_proc: flag=

2026-02-11 15:38:47.612: [apmaintain] [INFO][comm_uniform_send.c: comm_uniform_send_addr:145] uniform send success!

2026-02-11 15:38:47.613: [apmaintain] [INFO][msghandle.c:commu_msg_send_helper_cb:1107] Success to call

comm_uniform_send to report the message to DMP.

2026-02-11 15:41:10.314: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: get

2026-02-11 15:41:10.320: [elinkclt]

{"ctcpd.wifi":{"wifiqualitycollectswitch":255,"wifiswitch":"off","wpsswitch":"off","elinksync":"on","bandsteering":"off"}}

2026-02-11 15:41:10.321: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: set

2026-02-11 15:41:10.321: [elinkclt] {"wpsswitch":"on"}

2026-02-11 15:41:10.328: [elinkclt] {"result":"0"}

2026-02-11 15:43:24.449: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: get

2026-02-11 15:43:24.455: [elinkclt]

{"ctcpd.wifi":{"wifiqualitycollectswitch":255,"wifiswitch":"off","wpsswitch":"off","elinksync":"on","bandsteering":"off"}}

2026-02-11 15:43:24.456: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: set

2026-02-11 15:43:24.456: [elinkclt] {"wpsswitch":"on"}

2026-02-11 15:43:24.464: [elinkclt] {"result":"0"}

2026-02-11 15:49:10.231: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: get

2026-02-11 15:49:10.237: [elinkclt]

{"ctcpd.wifi":{"wifiqualitycollectswitch":255,"wifiswitch":"off","wpsswitch":"off","elinksync":"on","bandsteering":"off"}}

2026-02-11 15:49:10.237: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: set

2026-02-11 15:49:10.237: [elinkclt] {"wpsswitch":"on"}

2026-02-11 15:49:10.243: [elinkclt] {"result":"0"}

2026-02-11 15:49:45.366: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: get

2026-02-11 15:49:45.372: [elinkclt]

{"ctcpd.wifi":{"wifiqualitycollectswitch":255,"wifiswitch":"off","wpsswitch":"off","elinksync":"on","bandsteering":"off"}}

2026-02-11 15:49:45.372: [elinkclt] ubus_invoke_debug: o: ctcpd.wifi, m: set

2026-02-11 15:49:45.372: [elinkclt] {"wpsswitch":"on"}

2026-02-11 15:49:45.378: [elinkclt] {"result":"0"}

/ # Cannot find device "wan1_4096"

History

#1 - 03/17/2026 11:35 -

- Status changed from New to Resolved

- Assignee changed from to

#2 - 03/20/2026 16:24 -

- Status changed from Resolved to Closed

#2 SMP Wed Mar 18 18:49:44 CST 2026 ok