

# WIFI6\_AP - Bug #3968

web web

02/11/2026 16:44 -

<b>Status:</b>	Resolved	<b>Start date:</b>	02/11/2026
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Created:</b>	SMP Fri Feb 6 10:17:44 CST 2026	<b>Progress:</b>	100%

**Description**  
 1  
 2 web -- --  
 3  
 980 981  
 981

## History

#1 - 03/16/2026 18:43 -

- Status changed from New to Resolved

- Assignee changed from to

```
hi_os_system("ubus call ctcapd.initd restore");
```

#2 - 03/20/2026 16:40 -

- Status changed from Resolved to New

#2 SMP Wed Mar 18 18:49:44 CST 2026

#3 - 03/24/2026 16:18 -

- Status changed from New to Resolved

```
2026/3/24 / # ubus call ctcapd.initd status {
"ctcapd.initd": [
  {
    "name": "init.ctc",
    "version": "R938",
    "arch": "hi5671yv2",
    "buildtime": "2025-04-24 06:37:06",
    "uptime": 1499,
    "pid": 3096,
    "runtime": 1456
  },
  {
    "name": "appd",
    "version": "R980 (A936C970)",
    "pid": 3106,
    "runtime": 1456
  }
]
```