

WIFI6_AP - Bug #3976

3.11.3 MAC STA AP beacon rssi 0.

02/12/2026 11:38 -

Status:	New	Start date:	02/12/2026
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Created:	#2 SMP Fri Feb 6 10:17:44 CST 2026	Progress:	100%

Description

```

1
ubus call ctcapd.wifi.roaming startaprssiquery '{"mac":"32AEE3EFC27C","aps":[{"bssid":"4CC096286910","channel":5}]}'
1

```

Files

20260212113757.png	79.7 KB	02/12/2026	
20260212113846.png	83.6 KB	02/12/2026	