

# AML-SW3-WiFi6 - Bug #3985

ctcapd.devinfo

02/24/2026 11:36 -

<b>Status:</b> New	<b>Start date:</b> 02/24/2026
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b>	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b>	<b>Spent time:</b> 0.00 hour
<b>Created:</b> #7 SMP PREEMPT Tue Feb 10 14:35:51 CST 2026	<b>Progress:</b> 100%

## Description

```
1. ubus call ctcapd.devinfo set '{"workmode":"router"}'
2. ubus call ctcapd.devinfo get

2. curl -s -X GET http://192.168.2.1:8080/WEBUI/jsonrpc2?token=...&method=ctcapd_devinfo_get '{"workmode":"router"}'
{"ctcapd.devinfo":{"mac":"","vendor":"","model":"","swversion":"","hdversion":"","sn":"","ipaddr":"","url":"","wireless":"yes/no","dualband":"yes/no","triband":"yes/no","workmode":"router","suggestworkmode":"router/bridge/repeater/any","mesh":"0/1/2","usb":"yes/no","vpn":"yes/no","ifversion":"1.0","ctei":"","lanports":["eth0"],"wanports":["eth1"],"devtype":"","description":""}}
```