

VS057 - Bug #3217

2.4\5Gwifi WEB

02/21/2025 10:30 - 11:00

Status:	Resolved	Start date:	02/21/2025
Priority:	Normal	Due date:	
Assignee:	chuanjia liu	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Comments:	#2 SMP Fri Jan 17 17:24:00 CST 2025	Progress:	100%
Description			
问题描述 1.在虚拟机中安装Ubuntu 2.4G\5G镜像文件并启动 2.在虚拟机中安装Ubuntu 2.4G\5G镜像文件并启动 问题原因 1.web端无法访问虚拟机中的wifi模块 解决方案 1.web端无法访问虚拟机中的wifi模块			

History

#1 - 02/27/2025 14:54 - chuanjia liu

- Status changed from New to Resolved

Files

0000_20250221102028.png	146 KB	02/21/2025	
0000_20250221102459.png	140 KB	02/21/2025	
0000_20250221102451.png	200 KB	02/21/2025	