

1G\_wifi - Bug #3331

TR069 WAN X\_CT-COM\_PingResponseEnable WAN

04/02/2025 16:21

<b>Status:</b>	Feedback	<b>Start date:</b>	04/02/2025
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Number:</b>	20250401152636	<b>Progress:</b>	100%

**Description**

1. ITMS “IPv4/v6+VoIP”

VLAN1

a) WAN1 INTERNET

b) VLAN ID untag

c) IPv4/v6 PPPoE PPPoE RA WAN IPv6 GUA DHCP-PD DNS 56

VLAN2

a) WAN2 TR069\_VOICE

b) VLAN ID 46

c) IPv4 DHCPv4

ITMS WAN Internet WAN TR069\_Voice WAN index i;j

2. WAN1 IPv6 WAN1\_IPv6 WAN2 IPv4 WAN2\_IP

3. PC1 WAN1\_IPv6 IPv6 PC1\_IPv6

4. PC2 WAN2\_IP IPv4 PC2\_IP

5. PC1 ping -6 -S PC1\_IPv6 WAN1\_IPv6, PC2 ping -4 WAN2\_IP

6. ITMS

InternetGatewayDevice.WANDevice.1.WANConnectionDevice.{i}.WANPPPConnection.{i}. X\_CT-COM\_PingResponseEnable =true

InternetGatewayDevice.WANDevice.1.WANConnectionDevice.{j}.WANIPConnection.{j}. X\_CT-COM\_PingResponseEnable =true

7. 5

5. ping

7. ping

6 X\_CT-COM\_PingResponseEnable =true TR069 WAN WAN

History

- #1 - 04/02/2025 17:18 - tingwei huang
- Status changed from New to Feedback
- Assignee changed from tingwei huang to

wan wan