

# AML-SW3-WiFi6 - Bug #3739

[W3] 2G or 5G 802.11ax only , 11ac

10/22/2025 13:59 - sheng miao

<b>Status:</b>	Resolved	<b>Start date:</b>	10/22/2025
<b>Priority:</b>	High	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Version:</b>	v1.0.24-4737c241	<b>Progress:</b>	100%

## Description

- 2G 5G 802.11ax only
- 11ac (mix2s)
- 

1. mix mode ax only mode, start\_ap

cfg80211\_ap\_settings->

ht\_cap, vht\_cap, he\_cap, he\_oper, ht\_required, vht\_required, he\_required

2. tplink\_ax11000 ax6000 ax only mode Mix2s

## History

#1 - 10/27/2025 17:12 - sheng miao

- Status changed from New to Resolved

postponed

## Files

ax\_only\_mode.zip

28.3 KB

10/22/2025

sheng miao