

WIFI6_AP - Bug #3943

2.2.2 SSID 9

02/09/2026 17:40 -

Status:	New	Start date:	02/09/2026
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Created:	2 SMP Fri Feb 6 10:17:44 CST 2026	Updated:	100%

Description

- telnet
- ubus call ctcpd.appd list SSID
- SSID IoT
- ubus call qlink postmsg '{"CmdType":"SetQlinkConfig", "Sequnceld":"0a000001", "infos":{"enable":1, "timeLimit":300}}' SSID 300 timeLimit >= 180s
- ubus call qlink postmsg '{"CmdType":"GetQlinkConfig", "Sequnceld":"0a000007"}' SSID
- ubus call ctcpd.wifi.1.ap list 2.4G SSID IP 192.168.2.1 32769 IP LAN IP
- SSID ping
- IoT
- ubus call qlink postmsg '{"CmdType":"GetQlinkDevList", "Sequnceld":"3c0b0001"}' IoT SSID
- ubus call qlink postmsg '{"CmdType":"SetQlinkDev", "Sequnceld":"3c0b0005", "devList":[{"mac":"8C882B00000C", "action":"allow"}]}' IoT
- ubus call ctcpd.laninfo list IoT SSID
- IoT IoT

```

g
/ # ubus call qlink postmsg '{"linkType":"qlink", "CmdType":"GetQlinkDevList", "Sequnceld":"3c0b0001"}' {
"CmdType": "GetQlinkDevList",
"Sequnceld": "3c0b0001",
"Status": 0,
"devList": [
]
}
/ #

```

- 2 SSID
- 5
- 6 SSID IP
- 7 ping
- 9 IoT MAC
- 11 IoT SSID
- 12 IoT 20s