

WIFI6_AP - Bug #3951

1.3.6 eBPF, No ELF library support compiled in.

02/10/2026 15:11 -

Status:	Closed	Start date:	02/10/2026
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Created:	2 SMP Fri Feb 6 10:17:44 CST 2026	Progress:	100%

Description

```
telnet
test_ebpf.o bpftool /var/tmp
cd /var/tmp /var/tmp chmod +x bpftool
LAN1 PC
PC ping ip(192.168.2.1)
ifconfig LAN ip link set dev [LAN] xdp obj /var/tmp/test_ebpf.o sec xdp1
ip link set dev br0 xdp obj /var/tmp/test_ebpf.o sec xdp1
ip link set dev eth0 xdp obj /var/tmp/test_ebpf.o sec xdp1
PC ping ip(192.168.2.1)
cat /sys/kernel/debug/tracing/trace_pipe
./bpftool prog show MAP id map_ids Prog id xdp
./bpftool prog pin id [prog id] /sys/fs/bpf/test_ebpf
ls -l /sys/fs/bpf/test_ebpf
./bpftool prog dump jited id [prog id]
./bpftool map dump id [map id]
```

`/tmp # ip link set dev br0 xdp obj /tmp/test_ebpf.o sec xdp1`
No ELF library support compiled in.
`/tmp #`

History

- #1 - 03/06/2026 11:39 -
 - Status changed from New to Resolved
 - Assignee changed from to
- #2 - 03/20/2026 10:22 -
 - Assignee changed from to
- #3 - 03/26/2026 14:58 -
 - Status changed from Resolved to Closed