

AML-SW3-WiFi6 - Bug #3987

ctcapd.devinfo set

02/24/2026 11:45 -

Status: New	Start date: 02/24/2026
Priority: Normal	Due date:
Assignee:	% Done: 0%
Category:	Estimated time: 0.00 hour
Target version:	Spent time: 0.00 hour
Created: #7 SMP PREEMPT Tue Feb 10 14:35:51 CST 2026	Updated: 100%

Description

```
1. ubus call ctcapd.devinfo set '{"workmode":"router"}'
```

```
1. 1048 {"result":"0"}
```

```
#ubus call ctcapd.devinfo set '{"workmode":"router"}'
```

```
00:47:35 [ctcapd_server_m][Warn] [object_ctcapd_d(45)ubus_ctcapd_dev] ctcapd_devinfo_set.workmode=router
```

```
00:47:35 [ctcapd_server_m][Error] [networkingdev_m(450)pm_set_network_] modetype not change {
```

```
"result": "0",
```

```
"failreason": ""
```

```
}
```